

Measure Z Annual Report

Fiscal Year 2019 – 2020

City of Wildomar

FY 2019-20

Dustin Nigg, Mayor
Bridgette Moore, Mayor Pro Tem
Ben J. Benoit, Council Member
Joseph Morabito, Council Member
Marsha Swanson, Council Member

Gary Nordquist
City Manager

Thomas D. Jex
City Attorney

Measure Z Oversight and Advisory Committee

Steve Regalado, Chair
Shelley Hitchcock, Committee Member
Christopher Pselos, Committee Member
Timothy Underdown, Committee Member
Shelia Urlaub, Committee Member

Community Services and Parks Operations Staff

Daniel Torres, Parks and Community Services Manager
Christy Bowen, Grounds Worker II
Cameron Luna, Community Services Intern II
Les Chapman, Community and Emergency Services Specialist
Keith Ross, Code Enforcement Specialist
Janet Morales, Acting City Clerk

Table of Contents

Introduction.....	1
Wildomar Parks Description.....	3
Maintenance and Operations Report	5
Measure Z Funded Parks Special Events	10
Measure Z Oversight and Advisory Committee Comments Summary.....	17
Measure Z Oversight and Advisory Committee Comments	22
Financial Information.....	111



Introduction

The purpose of this report is to provide the City Council of the City of Wildomar with the amount of funds collected and expended, the status of the community parks and community park facilities, programs and services funded by the tax proceeds raised by Measure Z, including the costs of staff, utilities, materials, contract services and other items related to the repair and maintenance of community parks and community park facilities.

Specifically as stated in Ordinance 71 and Municipal Code section 3.18:

3.18.020 Purpose.

*The tax authorized by this chapter is solely for the purpose of raising revenue to pay for the availability of and the funding, repair, operating and maintenance of community parks and community park related facilities, programs and services within the City of Wildomar. The tax is not imposed as an ad valorem tax on real property, nor a transaction tax or sales tax on the sale of real property. The proceeds of the tax will be deposited in a special fund and shall be restricted for the purposes stated above. As such, the tax is a special tax. (Ord. 71 § 1, 2012)*¹

3.18.030 Use of proceeds.

Tax proceeds raised pursuant to this chapter may only be used for Wildomar community park purposes as specified in Section 3.18.020, including, but not limited to, maintaining clean public restrooms, maintaining safe playground equipment, restoring safety lighting, removing graffiti, maintaining sports fields, and maintaining landscaping and public structures situated in Wildomar community parks. Tax proceeds raised pursuant to this chapter may also be used for audit reports as set forth in this chapter. (Ord. 71 § 1, 2012)

3.18.040 Annual report.

An annual report shall be prepared and filed with the City Council of the City as provided in Sections 50075.1 and 50075.3 of the California [Government Code](#), and shall contain: (A) the amount of funds collected and expended; and (B) the status of the community park and community park facilities, programs and services funded by the tax proceeds raised pursuant to this chapter, including the costs of staff, utilities, materials, contract services and other items related to the repair and maintenance of community parks and community park facilities. (Ord. 71 § 1, 2012)

3.18.050 Annual audit. *The Director of Finance shall cause the City's independent auditor to perform an annual audit of the expenditure of the proceeds of the tax imposed by this chapter. (Ord. 71 § 1, 2012)*

On November 6, 2012, Wildomar residents voted and approved a \$28 annual parcel tax (Measure Z) to assist in the funding of park operations and related park activities. By Statute, the passage of Measure Z triggered a number of tasks, one of which was establishing the Parks Funding Measure Z Citizen's Oversight Advisory Committee. At the completion of the Fiscal Year 2019-20, the committee members were:

Steve Regalado, Chair
Shelley Hitchcock, Committee Member
Christopher Pselos, Committee Member
Timothy Underdown, Committee Member
Shelia Urlaub, Committee Member

Committee Meetings for FY 2019-20, were held:

- August 22, 2019
- December 03, 2019
- February 27, 2020
- June 11, 2020

This report includes a description of each of the four City of Wildomar parks, a report stating the Maintenance and Operations performed during the year, a recap of the Measure Z Funded Special Event, an assessment of the parks conditions and operations by each of the committee members and the Wildomar Measure Z Park Fund Financial Statements for the Year Ended June 30, 2020 as provided by the independent audit firm of Teaman, Ramirez & Smith, Inc. These financial statements serve as the final 4th quarter financial report completing the series of quarterly financial reports provide to the committee for review.


Description of Wildomar Parks

MARNA O'BRIEN PARK- *located at 20505 Palomar Street, this is the largest of the City parks with a size of 9 acres and is often the site of many of the City's special events. The park facilities consist of three baseball fields with spectator and player benches, two full basketball court, and two large multi-use soccer fields along with sports field lighting, a tot-lot, a Little Free Library, three picnic shelters, a concrete walking trail, parking lot and permanent restrooms and a concession stand which is used for special events.*

REGENCY HERITAGE PARK- *located at 20171 Autumn Oaks Place. This neighborhood park for the residents of Wildomar includes a tot lot play area, two basketball half courts, picnic shelters, park benches and a dog park. The park is designed with a direct access so that its facilities can be shared with neighborhood school.*

WINDSONG PARK- *located at 35459 Prairie Road. This neighborhood park is located in the Windsong area of Wildomar. The park includes tot lot, basketball court, a Little Free Library, concrete walkway around the perimeter of the park, picnic tables and picnic shelters.*

MALAGA PARK- *located at 32038 Mission Trail, the newest of the City parks and it serves as a gateway to the City of Wildomar when traveling from the City of Lake Elsinore. The park amenities include a perimeter walkway, lovely shade structures, a decorative rock feature near the Welcome to Wildomar/Malaga Park Monument, a Little Free Library, and has a beautiful view of the Cleveland National Forest Mountains.*



Maintenance and Operations Summary

The daily upkeep of the four city parks are performed by contracted landscape, janitorial, and security services. These services are vital to the overall appearance and maintenance of each park locations assets. City Staff performs a daily walk thru to confirm that the parks are at an adequate service level for use.

Throughout the year larger maintenance items and projects are conducted to provide the most utility from each park location. The following pages highlight these items as well as reporting the water usage for each park.

Marna O'Brien

During the Fiscal Year 19-20, shrub gardens throughout Marna O'Brien were replenished with fresh plants and bark.



The playground was topped off with certified woodchips upon the completion of CIP 053, Installation of Shade Structure.



As part of the annual turf maintenance, the sports field and park area were treated for the removal of broadleaf vegetation.

Water Usage

FY 17-18 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Commercial Meter	8	6	44	9	9	7	6	7	8	10	10	9
Irrigation Meter	1553	1589	983	1001	410	6	175	266	429	717	1033	1268
Total	1561	1595	1027	1010	419	13	181	273	437	727	1043	1277
FY 18-19 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Commercial Meter	9	10	10	12	8	6	5	5	8	9	10	10
Irrigation Meter	1565	1454	1243	332	272	1	0	0	303	727	584	1053
Total	1574	1464	1253	344	280	7	5	5	311	736	594	1063
FY 19-20 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Commercial Meter	9	12	10	9	5	4	6	6	5	2	6	7
Irrigation Meter	1883	1469	1087	617	219	0	14	47	8	312	988	940
Total	1892	1481	1097	626	224	4	20	53	13	314	994	947

Regency Heritage

Since the installation of the double gate entry to the dog parks, Heritage is receiving yearly maintenance to the DG hardscape.


Fence maintenance was performed within the drainage channel inlet from Trailwood Court.

Water Usage

FY 17-18 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter	0	0	0	0	0	0	0	0	4	45	73	46
FY 18-19 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter	34	132	52	0	0	0	0	0	1	1	0	1
FY 19-20 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter	0	0	7	0	0	0	0	0	1	0	0	0

Windsong

Along with Marna O'Brien Park, Windsong received playground bark replenishment upon completion of CIP 053.



As part of Windsong's tree maintenance program, the xylosma congestum parallel to the Oakmore Lane homes were trimmed along the fence line.

As part of the depreciation program, the concrete valve boxes throughout the park were replaced with the standard purple plastic valve boxes.

Water Usage

FY 17-18 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter	412	309	270	136	64	49	52	104	185	187	192	421
FY 18-19 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter	420	297	295	126	31	0	0	24	133	168	233	288
FY 19-20 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter	357	382	189	179	48	2	5	3	0	192	302	310

Malaga “Gateway” Park

After a full year of establishment, several plants, groundcover, and surface material were replenished.



Water Usage

FY 17-18 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter												
FY 18-19 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter					5	0	0	0	6	10	7	12
FY 19-20 Centum Cubic Feet Used												
	Jul	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar	Apr	May	Jun
Irrigation Meter	67	60	14	72	51	0	47	69	2	5	10	32



Measure Z Funded Special Events

**Parks
Make
Life
Better!**




	Event	When	Park	Expenditure	Revenue
1	City Birthday Celebration	Saturday, July 13, 2019	Marna O'Brien	7,099.00	3,216.67
2	Movie in the Park	Saturday, July 27, 2019	Marna O'Brien	718.00	666.67
3	Astronomy Night	Saturday, August 24, 2019	Marna O'Brien	-	666.67
4	Mariachi Night	Saturday, September 7, 2019	Marna O'Brien	5,479.00	1,166.67
5	Trunk or Treat	Saturday, October 26, 2019	Marna O'Brien	3,047.98	1,166.67
6	Eggstravaganza Egg Hunt	Saturday, April 04, 2020	Marna O'Brien	2,147.00	1,166.67
7	Teen Egg Hunt	Saturday, April 04, 2020	Marna O'Brien	Cancelled	666.67
8	Health Fair / ALS Run	Saturday, April 18, 2020	Marna O'Brien	Cancelled	666.67
9	Astronomy Night	Saturday, May 2, 2020	Marna O'Brien	Cancelled	666.67
10	Picnic in the Park	Saturday, June 6, 2020	Marna O'Brien	Cancelled	666.67
11	Movie in the Park	Saturday, June 13, 2020	Windsong	Cancelled	666.67
12	Campout in the Park	Sat / Sun, June 27-28, 2020	Marna O'Brien	Cancelled	666.67

City Birthday Celebration Saturday, July 13, 2019 Marna O'Brien Park



Celebrated the City's 11th birthday with live concert performance, bounce houses, food, drinks, vendors, and several activities for the kids.

- Expenditures: \$7,099.00
- Revenues: \$3,216.67
- Attendance: 500



Movie in the Park
Saturday, July 27, 2019
Marna O'Brien Park

The City of Wildomar Presents:

THE SECRET LIFE OF PETS

Saturday July 27, 2019

7 PM

Marna O'Brien Park

20505 Palomar Street
Wildomar, CA 92595



Rated PG

Join us for a free family movie night in the park to watch **The Secret Life of Pets!** Enjoy activities before the movie begins. Bring a blanket, snacks and chairs. Animal Friends of the Valleys will be selling food at the snack bar.

Activities will take place from 7:00PM-8:00PM.

Movie will begin at dusk.

For more information, contact Daniel Torres at
dtorres@cityofwildomar.org or 951-677-7751 x222



Movie in the Park event featured The Secret Life of Pet movie with a variety of children's activities before the movie.

- Expenditures: \$718.00
- Revenues: \$666.67
- Attendance: 150


Astronomy Night
Saturday, August 24, 2019
Marna O'Brien Park



Astronomy presentation by John Garrett from the Temecula Valley Astronomers (TVA) followed by a viewing of the night sky through telescopes provided by the TVA. Telescopes were given away during a free raffle provided by event sponsors.

- Expenditures: \$00.00
- Revenues: \$666.67
- Attendance: 200

*The image below was used to advertise the event.
Presented on the Inland Valley Hospital LED sign,
on the 15-freeway North before Clinton Keith.*



Mariachi Night

Saturday, September 7, 2019

Marna O'Brien Park

The City of Wildomar Presents:

MARIACHI NIGHT!

6pm - 10pm Saturday September 7, 2019
Marna O'Brien Park 20505 Palomar Street, Wildomar CA

Enjoy this free concert along with games, face painting, and other activities for the kids! St. Frances of Rome will be providing food available for purchase. Free Ice Cream while supplies last!

Questions? contact Daniel Torres at dtorres@cityofwildomar.org @CITYOFWILDOMAR.ORG

The themed Mariachi Night was a community favorite the previous year. This event was highly attended with multiple activities and food vendors available. This year's concert in the park featured an opening cover band and a Mariachi band.

- Expenditures: \$5,479.00
- Revenues: \$1,166.67
- Attendance: 700

WILDOMAR MARIACHI NIGHT!

Attendees were able to have their photo taken and printed with the decorative boarder to commemorate the event.

TAPSNAP® SOUTHWEST HEALTHCARE SYSTEM the senior generation Parks Make Life Better!

@CITYOFWILDOMAR.ORG #GOWILDOMAR September 7th, 2019 #MARIACHINIGHT WWW.CITYOFWILDOMAR.ORG

Trunk or Treat
Saturday, October 26, 2019
Marna O'Brien Park



This fun and safe event welcomes families to attend dressed in their favorite costumes and go trick-or-treating at the decorative trunks of local pre-authorized organizations and businesses. City also provided carnival booths, craft tables, a DJ and held contests for the best children's costumes and best decorated trunks.

- Expenditures: \$3,047.98
- Revenues: \$1,166.67
- Attendance: 800

*The image below was used to advertise the event.
Presented on the Wildomar Square LED sign,
on the 15-freeway South Clinton Keith off-ramp.*



Due to the COVID-19 pandemic and adhering to State and County restrictions, the following FY 19-20 Special Events were cancelled:

Eggstravaganza Egg Hunt
Saturday, April 04, 2020
Marna O'Brien Park

Teen Egg Hunt
Saturday, April 04, 2020
Marna O'Brien Park

Health Fair / ALS Run
Saturday, April 18, 2020
Marna O'Brien Park

Astronomy Night
Saturday May 02,2020
Marna O'Brien Park

Picnic in the Park
Saturday, June 06,2020
Marna O'Brien Park

Movie in the Park
Saturday, June 13, 2020
Windsong Park

Campout in the Park
Saturday, June 27-28, 2020
Marna O'Brien Park

Revenues for the 2020 Special Event calendar year were raised through the Community Services Sponsorship Participation Program. Early in the 2020 year, Pacific Dental Services LLC, Smile Generation, committed to a second year as a "Sponsor of the Year," generating a revenue of \$10,000.00 to be divided through all 15 Special Events for the calendar year.

Although canceled, the Eggstravaganza Event had an expenditure of \$2,147.00 to cover supplies purchased prior to the pandemic. Any unused funds will be carried over for the use of future Special Events.

Measure Z's Oversight and Advisory Committee Member Comments

Consistent with the requirements of City of Wildomar Municipal Code 3.18.040 – Annual Report, the following are comments from the Committee (presiding at 6-30-2017) regarding “...(a) the amount of funds collected and expended, and (b) the status of the community park and community park facilities, programs and services funded by the tax proceeds raised pursuant to this chapter, including the costs of staff, utilities, materials, contract services and other items related to the repair and maintenance of community parks and community park facilities.”

The first installment of this section is a summary of the combined Advisory Committee Member comments for each park location. The later pages are comments from each committee member:

Steve Regalado
Christopher Pselos
Timothy Underdown
Shelia Urlaub
Shelley Hitchcock



City of Wildomar
Measure Z - Parks Assessment Summary FY19-20
Marna O'Brien Park

	STEVE REGALADO		CHRISTOPHER PSELOS		TIMOTHY UNDERDOWN		SHEILA URLAUB		SHELLY HITCHCOCK	
	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority
1 Landscape Detail										
1.1 Turf Maintenance	A	4	A	2	A	4	E	4		
1.2 Shrub Gardens	A	4	E	4	A	4	A	4		
1.3 Trees	E	4	E	4	A	4	E	4		
1.4 Baseball Diamonds/ Dugouts/Bleachers	A	4	A	2	A	4	E	4		
2 Structural Detail										
2.1 Building Appearance	E	4	E	4	A	4	E	4		
2.2 Restrooms	A	4	E	4	E	4	E	4		
2.3 Snack Bar Area	A	4	E	4	A	2	E	4		
2.4 Gazebos	A	4	E	4	A	4	A	4		
2.5 Playground	E	4	E	4	A	4	E	4		
2.6 Water Tower	E	4	E	4	E	4	E	4		
2.7 Fencing	A	4	E	4	A	4	E	4		
3 Park Assets										
3.1 Basketball Courts	P	1	A	2	BA	1	A	4		
3.2 Exercise Equipment	A	4	E	4	A	4	E	4		
3.3 Parking Lot	A	4	E	4	A	4	E	4		
3.4 Light Poles	A	4	E	4	A	4	E	4		
3.5 Picnic Tables and Benches	A	4	E	4	A	4	A	4		
3.6 Drinking Fountains	A	4	E	4	E	4	E	4		
3.7 Trash Cans	A	4	E	4	A	4	A	4		
3.8 Dog Bag Dispenser	E	4	E	4	E	4	E	4		

***Rating**

E - Excellent A- Average BA - Below Average P - Poor

***Correction Priority**

1 - High 4 - Low



City of Wildomar
Measure Z - Parks Assessment Summary FY19-20
Windsong Park

	STEVE REGALADO		CHRISTOPHER PSELOS		TIMOTHY UNDERDOWN		SHEILA URLAUB		SHELLY HITCHCOCK	
	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority
1 Landscape Detail										
1.1 Turf Maintenance	A	4	A	2	A	4	E	4		
1.2 Shrub Gardens	A	4	E	4	A	4	E	4		
1.3 Trees	A	4	E	4	A	4	E	4		
1.4 Creek Garden	A	3	E	4	A	4	A	4		
2 Structural Detail										
2.1 Gazebos	A	4	E	4	A	4	E	4		
2.2 Playground	E	4	E	4	A	4	E	4		
2.3 Trash Cans	A	4	E	4	A	4	E	4		
2.4 Fencing	A	4	E	4	A	4	E	4		
3 Park Assets										
3.1 Basketball Courts	P	1	A	1	BA	1	A	4		
3.2 Light Poles	A	4	E	4	A	4	E	4		
3.3 Picnic Tables and Benches	A	4	E	4	A	4	A	4		
3.4 Dog Bag Dispenser	E	4	E	4	E	4	E	4		
3.5 Rocks	E	4	E	1	A	4	E	4		

***Rating**

E - Excellent A- Average BA - Below Average P - Poor

***Correction Priority**

1 - High 4 - Low



City of Wildomar
Measure Z - Parks Assessment Summary FY19-20
Heritage Regency Park

	STEVE REGALADO		CHRISTOPHER PSELOS		TIMOTHY UNDERDOWN		SHEILA URLAUB		SHELLY HITCHCOCK	
	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority
1 Landscape Detail										
1.1 Groundcover Maintenance	A	4	E	4	BA	3	BA	4		
1.2 Shrub Gardens	A	4	E	4	BA	2	A	4		
1.3 Trees	A	4	E	4	A	4	A	4		
1.4 Swale	A	4	E	4	BA	3	A	4		
2 Structural Detail										
2.1 Gazebos	A	4	E	4	BA	4	A	4		
2.2 Shade Structure	E	4	E	4	BA	4	A	4		
2.3 Playground	E	4	E	4	BA	2	E	4		
2.4 Dog Park	E	4	E	4	E	4	E	4		
2.5 Fencing	A	4	E	4	A	4	BA	1		
3 Park Assets										
3.1 Basketball Courts	A	4	E	4	A	3	A	4		
3.2 Picnic Tables and Benches	A	4	E	4	BA	4	E	4		
3.3 Trash Cans	A	4	E	4	A	4	E	4		
3.4 Dog Bag Dispenser	E	4	E	4	E	4	E	4		

***Rating**

E - Excellent A- Average BA - Below Average P - Poor

***Correction Priority**

1 - High 4 - Low



City of Wildomar
Measure Z - Parks Assessment Summary FY19-20
Malaga Park

		STEVE REGALADO		CHRISTOPHER PSELOS		TIMOTHY UNDERDOWN		SHEILA URLAUB		SHELLY HITCHCOCK	
		Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority	Rating	Correction Priority
1	Landscape Detail										
1.1	Groundcover and Tree Maintenance	E	4	E	4	E	4	A	4		
1.2	Shrub Gardens	E	4	E	4	E	4	E	4		
1.3	DG Walkway	E	4	E	4	E	4	E	4		
2	Structural Detail										
2.1	Shade Structures	A	4	E	4	A	4	E	4		
2.2	Signage	E	4	E	4	E	4	E	4		
2.3	Fencing	E	4	E	4	A	4	E	4		
3	Park Assets										
3.3	Benches and Trash Cans	A	4	E	4	A	4	E	4		

***Rating**

E - Excellent A- Average BA - Below Average P - Poor

***Correction Priority**

1 - High 4 - Low

Attachments

Measure Z Oversight Advisory Committee

July 2019 thru June 2020 Wildomar Parks Assessments

Provided by FY 2019-20 Committee Members:

Steve Regalado

Christopher Pselos

Timothy Underdown

Shelia Urlaub


ATTACHMENT A:

Steve Regalado
2020 Annual Parks
Inspection

City of Wildomar
Measure Z Oversight Advisory Committee

Wildomar Parks
Annual Inspection Guide

2019 / 2020



Steve Regalado, Chair
Shelly Hitchcock, Committee Member
Christopher Pselos, Committee Member
Timothy Underdown, Committee Member
Sheila Urlaub, Committee Memeber

Marna O'Brien Park
20505 Palomar Street
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the baseball diamonds and dugouts. Most of these locations are maintained by the parks landscape contractor.

1.1 Turf Maintenance

"Field" turf used by baseball, football, and soccer leagues.

"Park" turf found alongside the Gazebos and Tot lots.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrub gardens are located on the perimeter of the park and around the parking lot.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the trees on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Baseball Diamonds / Dugouts / Bleachers

There are 3-Baseball Diamonds; each with 2-Dugout and spectator bleachers.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

The structural detail pertains to the main building that is in the center of the park. The building contains two restrooms, a snack bar, and picnic benches. Also included in this detail are 3-Gazebos, Playground and Water Tower.

2.1 Building Appearance

This pertains to the overall appearance of the building such as paint, doors, benches, stainless roll-up doors, rain gutters, and vents.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Restrooms

Men's: 2-stalls and 1- urinal with 2-sinks

Women's: 3-stalls with 2-sinks

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Snack Bar Area

This area contains 2-roll up doors with counter tops and 4-Picnic Tables / Benches.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Gazebos

There are 3-Gazebos at this location; each with 2-Picnic Tables w/ Benches, BBQ's, and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.5 Playground

The Playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.6 Water Tower

The Water Tower is in the center of the parking lot in front of the main structure.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.7 Fencing

This consists of the vinyl fencing located along Palomar Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 Basketball Courts

This park contains 2-courts with 4-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Comments: <u>ALL 4 BASKETS IN DISREPAIR</u>				

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

3.2 Exercise Equipment

This location has 2-exercise devices located around the Park Turf area.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Comments: _____				

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Parking Lot

The parking lot has two entrances from Palomar and may hold up to 149 vehicles.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Comments: _____				

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Light Poles

The 71 light poles vary from 14 -20 feet tall with a plastic base cover. The poles are located throughout the park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.5 Picnic Tables and Benches

The Picnic Table are in the Gazebos, Snack Bar, and Park Turf.

The Bench are located around the Basketball Court, and Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.6 Drinking Fountains

The drinking fountains are located by the Snack Bar and Basketball Courts.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.7 Trash Cans

The Trash Cans are located at the Gazebos, Playground, Snack Bar, Basketball Court and Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.8 Dog Bag Dispenser

There are 3 – Dispensers in this park which are located around the Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Windsong Park
35459 Prairie Road
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the creek behind the chain link fence on the west side of the park. These areas are maintained by the parks landscape contractor.

1.1 Turf Maintenance

The turf at this park site is irrigated with reclaimed / recycled water from EVMWD.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The Shrub Gardens are located on the perimeter of this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the tree on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Creek Garden

This area is not accessible to the public. It is sectioned off by 450 linear feet of fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures that are on this location which consists of the Playground and 3-Gazebos.

2.1 Gazebos

There are 3-Gazebos at this location; Picnic Tables, BBQ's, and Trash Can. The Gazebo closest to the creek has 2-BBQ grills but does not contain any Picnic Tables to reduce vandalism.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Playground

The playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Trash Cans

The Trash Cans are in each of the Gazebos.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Fencing

This park location is sectioned off by chain link fencing. This detail consists of 450 linear feet that separate the west side creek, and 41 linear feet at the south entry.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 Basketball Court

This park contains 1-court with 2-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input checked="" type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: BOTH IN DISREPAIR

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

3.2 Light Poles

The 3-light poles on this location are 14ft tall and require a plastic base cover. The poles are found on the west side along the fence line.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Picnic Tables and Benches

The Picnic Table are in the Gazebos.

The Bench are located at the North Entry, and South of Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

There are 2 – Dispensers in this that are located at each entrance.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.5 Rocks

Surrounding the east side (Prairie Road) of this park location. There are 38 rocks that act as décor and safety barrier.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

**Heritage Regency Park
20171 Autumn Oak Place
Wildomar, CA. 92595**

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and the swale that runs along the entire park. These areas are maintained by the parks landscape contractor.

1.1 Groundcover Maintenance

This pertains to the 30,248 sq. ft. of vegetation that acts as groundcover. The reasoning behind the vegetation growth is to prevent dirt from washing into the swale during rain or rain runoff.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrubs area consists of hillside that is located around the north side wall and south side of the Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This pertains to the over health and appearance of the trees located on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenace.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Swale

This area pertains to the drain that runs along the 756 linear feet of park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenace.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures on this site that consist of the Playground, Gazebos and Shade Structure.

2.1 Gazebos

There are 2-Gazebos at this location; each with 3-Picnic Tables and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenace.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Shade Structure

The shade structure is in the center of the park with 3-Picnic Tables.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low	High
If not at satisfactory standard,	4	1

	Low	High
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>

2.3 Playground

The Playground is labeled for the age group of 5 -12 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low	High
If not at satisfactory standard,	4	1

	Low	High
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>

2.4 Dog Park

This area pertains to the 12,177sqft. of DG that is split into two separate sections:
Large Dogs and Small Dogs.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low	High
If not at satisfactory standard,	4	1

	Low	High
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>

2.5 Fencing

Most of this park is enclosed by chain link fencing. The Dog Park sectionals are also enclosed by black vinyl coated fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing

3.1 Basketball Court

This park contains 2-half courts with 2-hoops on a concrete surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: One net To Replace

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.2 Picnic Tables and Benches

The Picnic Tables are in Gazebos, and Shade Structure

The Benches are located around the Playground, East Walkway, Large Dog Park, Small Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Some graffiti

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Trash Cans

The Trash Cans are in the Gazebos, Shade Structure, and Large Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

The Dispensers are at the Autumn Oak entrance, and Small Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Malaga Park
32308 Mission Trail
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and bark. This detail also includes the DG walkway. This location is maintained by the parks landscape contractor.

1.1 Groundcover and Tree Maintenance

This pertains to the plants and Trees located throughout the park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrubs area are located along south perimeter of park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 DG Walkway

The pathway crosses through the center of the park starting on Wildomar Road leading up to Mission Trail.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low	High
If not at satisfactory standard,	4	1

	Low	High
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This section pertains to the Shade Structures and Concrete Sign on this park site.

2.1 Shade Structures

There are two standalone wooden pergolas.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: NEEDS REFINISHING

	Low	High
If not at satisfactory standard,	4	1

	Low	High
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>

2.2 Signage

This pertains to the curved concrete sign on the corner of Wildomar Road and Malaga.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low	High
If not at satisfactory standard,	4	1

	Low	High
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>

2.3 Fencing

This is pertaining to the wooden post and rope fencing along the Malaga Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. These items are serviced by the janitorial contractor.

3.1 Benches and Trash Cans

The benches and trash containers are located under each wooden pergola.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

ATTACHMENT B:

Christopher Pselos
2020 Annual Parks
Inspection

City of Wildomar
Measure Z Oversight Advisory Committee

Wildomar Parks
Annual Inspection Guide

2019 / 2020



Steve Regalado, Chair
Shelly Hitchcock, Committee Member
Christopher Pselos, Committee Member
Timothy Underdown, Committee Member
Sheila Urlaub, Committee Memeber

Marna O'Brien Park
20505 Palomar Street
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the baseball diamonds and dugouts. Most of these locations are maintained by the parks landscape contractor.

1.1 Turf Maintenance

"Field" turf used by baseball, football, and soccer leagues.

"Park" turf found alongside the Gazebos and Tot lots.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Overall the turf was green and plush. Near the far baseball field, there was some large brown areas as well as several gopher mounds.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrub gardens are located on the perimeter of the park and around the parking lot.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the trees on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Baseball Diamonds / Dugouts / Bleachers

There are 3-Baseball Diamonds; each with 2-Dugout and spectator bleachers.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

The structural detail pertains to the main building that is in the center of the park. The building contains two restrooms, a snack bar, and picnic benches. Also included in this detail are 3-Gazebos, Playground and Water Tower.

2.1 Building Appearance

This pertains to the overall appearance of the building such as paint, doors, benches, stainless roll-up doors, rain gutters, and vents.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Restrooms

Men's: 2-stalls and 1- urinal with 2-sinks

Women's: 3-stalls with 2-sinks

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Snack Bar Area

This area contains 2-roll up doors with counter tops and 4-Picnic Tables / Benches.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Gazebos

There are 3-Gazebos at this location; each with 2-Picnic Tables w/ Benches, BBQ's, and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.5 Playground

The Playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.6 Water Tower

The Water Tower is in the center of the parking lot in front of the main structure.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.7 Fencing

This consists of the vinyl fencing located along Palomar Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 **PARK ASSETS**

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 **Basketball Courts**

This park contains 2-courts with 4-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: 2 of the 4 backboards were missing, and nets were not present on remaining 2 backboards.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

3.2 **Exercise Equipment**

This location has 2-exercise devices located around the Park Turf area.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments:

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 **Parking Lot**

The parking lot has two entrances from Palomar and may hold up to 149 vehicles.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments:

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Light Poles

The 71 light poles vary from 14 -20 feet tall with a plastic base cover. The poles are located throughout the park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.5 Picnic Tables and Benches

The Picnic Table are in the Gazebos, Snack Bar, and Park Turf.

The Bench are located around the Basketball Court, and Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.6 Drinking Fountains

The drinking fountains are located by the Snack Bar and Basketball Courts.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.7 Trash Cans

The Trash Cans are located at the Gazebos, Playground, Snack Bar, Basketball Court and Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.8 Dog Bag Dispenser

There are 3 – Dispensers in this park which are located around the Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Windsong Park
35459 Prairie Road
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the creek behind the chain link fence on the west side of the park. These areas are maintained by the parks landscape contractor.

1.1 Turf Maintenance

The turf at this park site is irrigated with reclaimed / recycled water from EVMWD.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: A little more attention could be paid to maintenance of turf, but overall looked good.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The Shrub Gardens are located on the perimeter of this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the tree on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard,				
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Creek Garden

This area is not accessible to the public. It is sectioned off by 450 linear feet of fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard,				
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures that are on this location which consists of the Playground and 3-Gazebos.

2.1 Gazebos

There are 3-Gazebos at this location; Picnic Tables, BBQ's, and Trash Can. The Gazebo closest to the creek has 2-BBQ grills but does not contain any Picnic Tables to reduce vandalism.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard,				
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Playground

The playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Trash Cans

The Trash Cans are in each of the Gazebos.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Fencing

This park location is sectioned off by chain link fencing. This detail consists of 450 linear feet that separate the west side creek, and 41 linear feet at the south entry.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 **PARK ASSETS**

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 **Basketball Court**

This park contains 1-court with 2-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: No backboards were present.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

3.2 **Light Poles**

The 3-light poles on this location are 14ft tall and require a plastic base cover. The poles are found on the west side along the fence line.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 **Picnic Tables and Benches**

The Picnic Table are in the Gazebos.

The Bench are located at the North Entry, and South of Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

There are 2 – Dispensers in this that are located at each entrance.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.5 Rocks

Surrounding the east side (Prairie Road) of this park location. There are 38 rocks that act as décor and safety barrier.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

**Heritage Regency Park
20171 Autumn Oak Place
Wildomar, CA. 92595**

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and the swale that runs along the entire park. These areas are maintained by the parks landscape contractor.

1.1 Groundcover Maintenance

This pertains to the 30,248 sq. ft. of vegetation that acts as groundcover. The reasoning behind the vegetation growth is to prevent dirt from washing into the swale during rain or rain runoff.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrubs area consists of hillside that is located around the north side wall and south side of the Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This pertains to the over health and appearance of the trees located on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Swale

This area pertains to the drain that runs along the 756 linear feet of park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures on this site that consist of the Playground, Gazebos and Shade Structure.

2.1 Gazebos

There are 2-Gazebos at this location; each with 3-Picnic Tables and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: No restroom facilities present.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Shade Structure

The shade structure is in the center of the park with 3-Picnic Tables.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Playground

The Playground is labeled for the age group of 5 -12 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Dog Park

This area pertains to the 12,177sqft. of DG that is split into two separate sections:
Large Dogs and Small Dogs.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.5 Fencing

Most of this park is enclosed by chain link fencing. The Dog Park sectionals are also enclosed by black vinyl coated fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing

3.1 Basketball Court

This park contains 2-half courts with 2-hoops on a concrete surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.2 Picnic Tables and Benches

The Picnic Tables are in Gazebos, and Shade Structure

The Benches are located around the Playground, East Walkway, Large Dog Park, Small Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Trash Cans

The Trash Cans are in the Gazebos, Shade Structure, and Large Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

The Dispensers are at the Autumn Oak entrance, and Small Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Malaga Park
32308 Mission Trail
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and bark. This detail also includes the DG walkway. This location is maintained by the parks landscape contractor.

1.1 Groundcover and Tree Maintenance

This pertains to the plants and Trees located throughout the park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Parking area needs to be more defined.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrubs area are located along south perimeter of park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 DG Walkway

The pathway crosses through the center of the park starting on Wildomar Road leading up to Mission Trail.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This section pertains to the Shade Structures and Concrete Sign on this park site.

2.1 Shade Structures

There are two standalone wooden pergolas.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Signage

This pertains to the curved concrete sign on the corner of Wildomar Road and Malaga.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Fencing

This is pertaining to the wooden post and rope fencing along the Malaga Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. These items are serviced by the janitorial contractor.

3.1 Benches and Trash Cans

The benches and trash containers are located under each wooden pergola.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>


ATTACHMENT C:

Timothy Underdown 2020 Annual Parks Inspection

City of Wildomar
Measure Z Oversight Advisory Committee

Wildomar Parks
Annual Inspection Guide

2019 / 2020



Steve Regalado, Chair
Shelly Hitchcock, Committee Member
Christopher Pselos, Committee Member
Timothy Underdown, Committee Member
Sheila Urlaub, Committee Memeber

Marna O'Brien Park
20505 Palomar Street
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the baseball diamonds and dugouts. Most of these locations are maintained by the parks landscape contractor.

1.1 Turf Maintenance

"Field" turf used by baseball, football, and soccer leagues.

"Park" turf found alongside the Gazebos and Tot lots.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Comments: _____				

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrub gardens are located on the perimeter of the park and around the parking lot.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Comments: _____				

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the trees on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

1.4 Baseball Diamonds / Dugouts / Bleachers

There are 3-Baseball Diamonds; each with 2-Dugout and spectator bleachers.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Dugouts need weeds removed. _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

2.0 STRUCTURAL DETAIL

The structural detail pertains to the main building that is in the center of the park. The building contains two restrooms, a snack bar, and picnic benches. Also included in this detail are 3-Gazebos, Playground and Water Tower.

2.1 Building Appearance

This pertains to the overall appearance of the building such as paint, doors, benches, stainless roll-up doors, rain gutters, and vents.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

2.2 Restrooms

Men's: 2-stalls and 1- urinal with 2-sinks

Women's: 3-stalls with 2-sinks

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Better than most park bathrooms.

(I visit allot of parks doing little league.)

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Snack Bar Area

This area contains 2-roll up doors with counter tops and 4-Picnic Tables / Benches.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Concrete area around snack bar needs to be cleaned or presure washed, it is the first thing you notice when entering the park.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

2.4 Gazebos

There are 3-Gazebos at this location; each with 2-Picnic Tables w/ Benches, BBQ's, and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments:

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.5 Playground

The Playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.6 Water Tower

The Water Tower is in the center of the parking lot in front of the main structure.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.7 Fencing

This consists of the vinyl fencing located along Palomar Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 Basketball Courts

This park contains 2-courts with 4-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Need backboards replaced on 2 courts and hoop & nets replaced on all 4 courts.

(I realize they were probably taken down because of Covid but should be back up now with the new county rules.)

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

3.2 Exercise Equipment

This location has 2-exercise devices located around the Park Turf area.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Parking Lot

The parking lot has two entrances from Palomar and may hold up to 149 vehicles.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Light Poles

The 71 light poles vary from 14 -20 feet tall with a plastic base cover. The poles are located throughout the park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenace.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: I went by the park on 8/5/2020 at 9:00pm and the only lights on were the lights on the building, not sure if they are off for a reason.

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.5 Picnic Tables and Benches

The Picnic Table are in the Gazebos, Snack Bar, and Park Turf.
The Bench are located around the Basketball Court, and Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenace.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments:

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.6 Drinking Fountains

The drinking fountains are located by the Snack Bar and Basketball Courts.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenace.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments:

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.7 Trash Cans

The Trash Cans are located at the Gazebos, Playground, Snack Bar, Basketball Court and Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

3.8 Dog Bag Dispenser

There are 3 – Dispensers in this park which are located around the Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: They were all full when I did this inspection on 8/5/2020

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

Windsong Park
35459 Prairie Road
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the creek behind the chain link fence on the west side of the park. These areas are maintained by the parks landscape contractor.

1.1 Turf Maintenance

The turf at this park site is irrigated with reclaimed / recycled water from EVMWD.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Comments: _____				

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The Shrub Gardens are located on the perimeter of this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Comments: _____				

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the tree on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

1.4 Creek Garden

This area is not accessible to the public. It is sectioned off by 450 linear feet of fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures that are on this location which consists of the Playground and 3-Gazebos.

2.1 Gazebos

There are 3-Gazebos at this location; Picnic Tables, BBQ's, and Trash Can. The Gazebo closest to the creek has 2-BBQ grills but does not contain any Picnic Tables to reduce vandalism.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

2.2 Playground

The playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

2.3 Trash Cans

The Trash Cans are in each of the Gazebos.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

2.4 Fencing

This park location is sectioned off by chain link fencing. This detail consists of 450 linear feet that separate the west side creek, and 41 linear feet at the south entry.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 Basketball Court

This park contains 1-court with 2-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Need backboard, hoop and net replaced.

(Again I am sure these were taken down due to Covid but need to be replace now)

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

3.2 Light Poles

The 3-light poles on this location are 14ft tall and require a plastic base cover. The poles are found on the west side along the fence line.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Picnic Tables and Benches

The Picnic Table are in the Gazebos.

The Bench are located at the North Entry, and South of Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

There are 2 – Dispensers in this that are located at each entrance.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: It was full when I did the inspection on 8/5/2020

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

3.5 Rocks

Surrounding the east side (Prairie Road) of this park location. There are 38 rocks that act as décor and safety barrier.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

**Heritage Regency Park
20171 Autumn Oak Place
Wildomar, CA. 92595**

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and the swale that runs along the entire park. These areas are maintained by the parks landscape contractor.

1.1 Groundcover Maintenance

This pertains to the 30,248 sq. ft. of vegetation that acts as groundcover. The reasoning behind the vegetation growth is to prevent dirt from washing into the swale during rain or rain runoff.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Some of the ground cover is in need of more water.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrubs area consists of hillside that is located around the north side wall and south side of the Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: The shrubs on the south (School side) need more water.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

1.3 Trees

This pertains to the over health and appearance of the trees located on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Swale

This area pertains to the drain that runs along the 756 linear feet of park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Needs weeds removed from swale. _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures on this site that consist of the Playground, Gazebos and Shade Structure.

2.1 Gazebos

There are 2-Gazebos at this location; each with 3-Picnic Tables and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Gazebos need paint removed that covers graffiti, looks like they presure washed the ones at Windsong and that looks better. The picnic tables need to be replaced, one is bent (Table as you enter from the school side) and the others are burt or something. _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Shade Structure

The shade structure is in the center of the park with 3-Picnic Tables.

Please rate the overall appearance and maintenance.

Poor	Below Average	Average	Excellent
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Tables need replaced, the ones at Marna by the snack bar look more durable.

Very low priority but should be looked into in the future if funds become available.

(Or another scouting project)

If not at satisfactory standard,
Please rate the Level of Priority

Low			High
4	3	2	1
<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Playground

The Playground is labeled for the age group of 5 -12 years old.

Please rate the overall appearance and maintenance.

Poor	Below Average	Average	Excellent
<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Need shade covering over playground like at Marna and Windsong.

If not at satisfactory standard,
Please rate the Level of Priority

Low			High
4	3	2	1
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

2.4 Dog Park

This area pertains to the 12,177sqft. of DG that is split into two separate sections:
Large Dogs and Small Dogs.

Please rate the overall appearance and maintenance.

Poor	Below Average	Average	Excellent
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Dog park looks great and maintained very well.

If not at satisfactory standard,
Please rate the Level of Priority

Low			High
4	3	2	1
<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.5 Fencing

Most of this park is enclosed by chain link fencing. The Dog Park sectionals are also enclosed by black vinyl coated fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing

3.1 Basketball Court

This park contains 2-half courts with 2-hoops on a concrete surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Need net replaced on one court replaced. _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input checked="" type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

3.2 Picnic Tables and Benches

The Picnic Tables are in Gazebos, and Shade Structure

The Benches are located around the Playground, East Walkway, Large Dog Park, Small Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Tables need replaced as previously stated, Benches look good. _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input checked="" type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

3.3 Trash Cans

The Trash Cans are in the Gazebos, Shade Structure, and Large Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

The Dispensers are at the Autumn Oak entrance, and Small Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Both dispensers were full when i did this inspection on 8/5/2020

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Malaga Park
32308 Mission Trail
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and bark. This detail also includes the DG walkway. This location is maintained by the parks landscape contractor.

1.1 Groundcover and Tree Maintenance

This pertains to the plants and Trees located throughout the park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

1.2 Shrub Gardens

The shrubs area are located along south perimeter of park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

1.3 DG Walkway

The pathway crosses through the center of the park starting on Wildomar Road leading up to Mission Trail.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This section pertains to the Shade Structures and Concrete Sign on this park site.

2.1 Shade Structures

There are two standalone wooden pergolas.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Signage

This pertains to the curved concrete sign on the corner of Wildomar Road and Malaga.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard, Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Fencing

This is pertaining to the wooden post and rope fencing along the Malaga Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. These items are serviced by the janitorial contractor.

3.1 Benches and Trash Cans

The benches and trash containers are located under each wooden pergola.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard, Please rate the Level of Priority	4 <input type="radio"/>	3 <input type="radio"/>	2 <input type="radio"/>	1 <input type="radio"/>

ATTACHMENT D:

Sheila Urlaub
2020 Annual Parks
Inspection

City of Wildomar
Measure Z Oversight Advisory Committee

Wildomar Parks
Annual Inspection Guide

2019 / 2020



Steve Regalado, Chair
Shelly Hitchcock, Committee Member
Christopher Pselos, Committee Member
Timothy Underdown, Committee Member
Sheila Urlaub, Committee Memeber

Marna O'Brien Park
20505 Palomar Street
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the baseball diamonds and dugouts. Most of these locations are maintained by the parks landscape contractor.

1.1 Turf Maintenance

"Field" turf used by baseball, football, and soccer leagues.

"Park" turf found alongside the Gazebos and Tot lots.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Gopher activity.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrub gardens are located on the perimeter of the park and around the parking lot.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Needs Trimming.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the trees on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Baseball Diamonds / Dugouts / Bleachers

There are 3-Baseball Diamonds; each with 2-Dugout and spectator bleachers.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Some graffiti issues on walls near back dugout.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

The structural detail pertains to the main building that is in the center of the park. The building contains two restrooms, a snack bar, and picnic benches. Also included in this detail are 3-Gazebos, Playground and Water Tower.

2.1 Building Appearance

This pertains to the overall appearance of the building such as paint, doors, benches, stainless roll-up doors, rain gutters, and vents.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Restrooms

Men's: 2-stalls and 1- urinal with 2-sinks

Women's: 3-stalls with 2-sinks

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Snack Bar Area

This area contains 2-roll up doors with counter tops and 4-Picnic Tables / Benches.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Gazebos

There are 3-Gazebos at this location; each with 2-Picnic Tables w/ Benches, BBQ's, and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.5 Playground

The Playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.6 Water Tower

The Water Tower is in the center of the parking lot in front of the main structure.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.7 Fencing

This consists of the vinyl fencing located along Palomar Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 **PARK ASSETS**

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 **Basketball Courts**

This park contains 2-courts with 4-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.2 **Exercise Equipment**

This location has 2-exercise devices located around the Park Turf area.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 **Parking Lot**

The parking lot has two entrances from Palomar and may hold up to 149 vehicles.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Light Poles

The 71 light poles vary from 14 -20 feet tall with a plastic base cover. The poles are located throughout the park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.5 Picnic Tables and Benches

The Picnic Table are in the Gazebos, Snack Bar, and Park Turf.

The Bench are located around the Basketball Court, and Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.6 Drinking Fountains

The drinking fountains are located by the Snack Bar and Basketball Courts.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.7 Trash Cans

The Trash Cans are located at the Gazebos, Playground, Snack Bar, Basketball Court and Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.8 Dog Bag Dispenser

There are 3 – Dispensers in this park which are located around the Field Turf walkway.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Windsong Park
35459 Prairie Road
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by turf, trees, shrubs, and bark. This detail also includes the creek behind the chain link fence on the west side of the park. These areas are maintained by the parks landscape contractor.

1.1 Turf Maintenance

The turf at this park site is irrigated with reclaimed / recycled water from EVMWD.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Minimal gopher issues.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The Shrub Gardens are located on the perimeter of this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This section pertains to the overall health and appearance of the tree on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard,				
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Creek Garden

This area is not accessible to the public. It is sectioned off by 450 linear feet of fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard,				
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures that are on this location which consists of the Playground and 3-Gazebos.

2.1 Gazebos

There are 3-Gazebos at this location; Picnic Tables, BBQ's, and Trash Can. The Gazebo closest to the creek has 2-BBQ grills but does not contain any Picnic Tables to reduce vandalism.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
	4	3	2	1
If not at satisfactory standard,				
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Playground

The playground is for the age group of 2-5 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: The shade cover looks great!

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Trash Cans

The Trash Cans are in each of the Gazebos.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments:

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Fencing

This park location is sectioned off by chain link fencing. This detail consists of 450 linear feet that separate the west side creek, and 41 linear feet at the south entry.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments:

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. Most of these items are serviced by the janitorial contractor.

3.1 Basketball Court

This park contains 1-court with 2-hoops on a Plexi-pave surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.2 Light Poles

The 3-light poles on this location are 14ft tall and require a plastic base cover. The poles are found on the west side along the fence line.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Picnic Tables and Benches

The Picnic Table are in the Gazebos.

The Bench are located at the North Entry, and South of Playground.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: One of the tables in the gazebo nearest the restroom look as if they have been cut.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

There are 2 – Dispensers in this that are located at each entrance.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.5 Rocks

Surrounding the east side (Prairie Road) of this park location. There are 38 rocks that act as décor and safety barrier.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: 44 rocks. _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Heritage Regency Park
20171 Autumn Oak Place
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and the swale that runs along the entire park. These areas are maintained by the parks landscape contractor.

1.1 Groundcover Maintenance

This pertains to the 30,248 sq. ft. of vegetation that acts as groundcover. The reasoning behind the vegetation growth is to prevent dirt from washing into the swale during rain or rain runoff.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: Unkept, not recently mowed. The ground cover is brown but that is to be expected right now.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrubs area consists of hillside that is located around the north side wall and south side of the Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Dry and brown.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 Trees

This pertains to the over health and appearance of the trees located on this park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.4 Swale

This area pertains to the drain that runs along the 756 linear feet of park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This detail is based on the main structures on this site that consist of the Playground, Gazebos and Shade Structure.

2.1 Gazebos

There are 2-Gazebos at this location; each with 3-Picnic Tables and Trash Can.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: It looks as if there is a constant battle with graffiti.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Shade Structure

The shade structure is in the center of the park with 3-Picnic Tables.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: Same problem with chronic graffiti.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Playground

The Playground is labeled for the age group of 5 -12 years old.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments:

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.4 Dog Park

This area pertains to the 12,177sqft. of DG that is split into two separate sections: Large Dogs and Small Dogs.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: It looks the best I have ever seen it. Entrance to large dog park a bit difficult to open.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.5 Fencing

Most of this park is enclosed by chain link fencing. The Dog Park sectionals are also enclosed by black vinyl coated fencing.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Comments: The fencing at north end, outside of dog park is torn down. Looks like a "party" area.
Well worn path to it and bottles strewn about.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing

3.1 Basketball Court

This park contains 2-half courts with 2-hoops on a concrete surface.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: It looks as if someone has been doing donuts on the court.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.2 Picnic Tables and Benches

The Picnic Tables are in Gazebos, and Shade Structure

The Benches are located around the Playground, East Walkway, Large Dog Park, Small Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: Same graffiti issue.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.3 Trash Cans

The Trash Cans are in the Gazebos, Shade Structure, and Large Dog Park

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.4 Dog Bag Dispenser

The Dispensers are at the Autumn Oak entrance, and Small Dog Park.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Malaga Park
32308 Mission Trail
Wildomar, CA. 92595

1.0 LANDSCAPE DETAIL

The landscape detail consists of areas that are covered by groundcover, trees, shrubs, and bark. This detail also includes the DG walkway. This location is maintained by the parks landscape contractor.

1.1 Groundcover and Tree Maintenance

This pertains to the plants and Trees located throughout the park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>

Comments: A little brown and some trash, overall good.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.2 Shrub Gardens

The shrubs area are located along south perimeter of park site.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments:

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

1.3 DG Walkway

The pathway crosses through the center of the park starting on Wildomar Road leading up to Mission Trail.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: I do wonder about where the trail ends at the south/west end of the park, is that private property? Often I will see a car parked butt up against the trail so as to make it impassible if someone in a wheelchair was using the trail.

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.0 STRUCTURAL DETAIL

This section pertains to the Shade Structures and Concrete Sign on this park site.

2.1 Shade Structures

There are two standalone wooden pergolas.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.2 Signage

This pertains to the curved concrete sign on the corner of Wildomar Road and Malaga.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

2.3 Fencing

This is pertaining to the wooden post and rope fencing along the Malaga Street.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

3.0 PARK ASSETS

This category consists of park assets that require maintenance or servicing. These items are serviced by the janitorial contractor.

3.1 Benches and Trash Cans

The benches and trash containers are located under each wooden pergola.

	Poor	Below Average	Average	Excellent
Please rate the overall appearance and maintenance.	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Comments: _____

	Low			High
If not at satisfactory standard,	4	3	2	1
Please rate the Level of Priority	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>

Annual Financial Summary

Total Measure Z revenues for FY 2019-20 were \$381,399, a increase of \$4,102 from last year's \$377,297. The expenditures were \$358,970, which is an increase of \$9,280 from \$349,690. Expenditures increase primarily due increase in contractual services.

The fund balance on June 30, 2020 was \$263,153, an increase of \$22,429 from last year's \$2240,724. From that balance twenty percent (20%), or \$70,000 of the audited year's expenditure amount is reserved to cover operating expenditures. An additional \$20,000 is reserved for utility cost stabilization. The remaining \$173,153 is applied towards the cost of repair and maintenance of longer-term depreciable park amenities and facilities.

The following pages are the Audited Financial Statements from Teaman, Ramirez and Smith, Inc., the City's external auditors.

**WILDOMAR MEASURE Z PARK FUND
CITY OF WILDOMAR, CALIFORNIA**

FUND FINANCIAL STATEMENTS

For the Year Ended June 30, 2020

Prepared By:

**The City of Wildomar
Finance Department**

**Wildomar Measure Z Park Fund
Fund Financial Statements
Year Ended June 30, 2020**

TABLE OF CONTENTS

	<u>PAGE</u>
Independent Auditors' Report	1 - 2
Basic Financial Statements:	
Fund Financial Statements	
Balance Sheet - Governmental Fund	3
Statement of Revenues, Expenditures and Changes in Fund Balances - Governmental Fund	4
Notes to Financial Statements	5 - 9
Required Supplementary Information:	
Notes to Required Supplementary Information	10
Budgetary Comparison Schedule	11

INDEPENDENT AUDITORS' REPORT

To the Honorable Mayor and Members
of the City Council
City of Wildomar, California

Report on Financial Statements

We have audited the accompanying financial statements of the Measure Z Park Fund, a special revenue fund of the City of Wildomar, California, as of and for the year ended June 30, 2020, and the related notes to the financial statements, which collectively comprise the Measure Z Park Fund's basic financial statements as listed in the table of contents.

Management's Responsibility for the Financial Statements

Management is responsible for the preparation and fair presentation of these financial statements in accordance with accounting principles generally accepted in the United States of America; this includes the design, implementation, and maintenance of internal control relevant to the preparation and fair presentation of financial statements that are free from material misstatement, whether due to fraud or error.

Auditor's Responsibility

Our responsibility is to an express opinion on these financial statements based on our audit. We conducted our audit in accordance with auditing standards generally accepted in the United States of America and the standards applicable to financial audits contained in *Government Auditing Standards*, issued by the Comptroller General of the United States. Those standards require that we plan and perform the audit to obtain reasonable assurance whether the financial statements are free from material misstatement.

An audit involves performing procedures to obtain audit evidence about the amounts and disclosures in the financial statements. The procedures selected depend on the auditor's judgment, including the assessment of the risks of material misstatement of the financial statements, whether due to fraud or error. In making those risk assessments, the auditor considers internal control relevant to the City's preparation and fair presentation of the financial statements in order to design audit procedures that are appropriate in the circumstances, but not for the purpose of expressing an opinion on the effectiveness of the City's internal control. Accordingly, we express no such opinion. An audit also includes evaluating the appropriateness of accounting policies used and the reasonableness of significant accounting estimates made by management, as well as evaluating the overall presentation of the financial statements.

We believe that the audit evidence we have obtained is sufficient and appropriate to provide a basis for our audit opinion.

Opinion

In our opinion, the financial statements referred to above present fairly, in all material respects, the respective financial position of the Measure Z Park Fund, as of June 30, 2020, and the respective changes in financial position for the year then ended in accordance with accounting principles generally accepted in the United States of America.

Emphasis of Matter

As discussed in Note 1 to the financial statements, the financial statements present only the Measure Z Park Special Revenue Fund, and do not purport to, and do not present the financial position of the City of Wildomar, California, as of June 30, 2020, the changes in its financial position for the year then ended in accordance with accounting principles generally accepted in the United States of America. Our opinion is not modified with respect to this matter.

Other Matters

Required Supplementary Information

Accounting principles generally accepted in the United States of America require that the Budgetary Comparison Schedule, as listed in the table of contents, be presented to supplement the financial statements. Such information, although not a part of the financial statements, is required by the Governmental Accounting Standards Board who consider it to be an essential part of the financial reporting for placing the financial statements in an appropriate operational, economic, or historical context. We have applied certain limited procedures to the required supplementary information in accordance with auditing standards generally accepted in the United States of America, which consisted of inquiries of management about the methods of preparing the information and comparing the information for consistency with management's responses to our inquiries, the financial statements, and other knowledge we obtained during our audit of the financial statements. We do not express an opinion or provide any assurance on the information because the limited procedures do not provide us with sufficient evidence to express an opinion or provide any assurance.

Management has omitted the management's discussion and analysis that accounting principles generally accepted in the United States of America require to be presented to supplement the basic financial statements. Such missing information, although not a part of the basic financial statements, is required by the Governmental Accounting Standards Board, who considers it to be an essential part of financial reporting for placing the basic financial statements in an appropriate operational, economic, or historical context. Our opinion on the basic financial statements is not affected by this missing information.

Other Reporting Required by Government Auditing Standards

In accordance with *Government Auditing Standards*, we have also issued our report dated February 4, 2021, on our consideration of the City's internal control over financial reporting and on our tests of its compliance with certain provisions of laws, regulations, contracts, and grant agreements and other matters. The purpose of that report is solely to describe the scope of our testing of internal control over financial reporting and compliance and the results of that testing, and not to provide an opinion on the effectiveness of the City's internal control over financial reporting or on compliance. That report is an integral part of an audit performed in accordance with *Government Auditing Standards* in considering the City's internal control over financial reporting and compliance.

Isaman Ramirez & Smith, Inc.

Riverside, California
February 4, 2021

BASIC FINANCIAL STATEMENTS

Wildomar Measure Z Park Fund
Balance Sheet
Governmental Fund
June 30, 2020

ASSETS

Due from Other Governments	\$ 25,619
Due from City	266,480
	<hr/>
Total Assets	\$ 292,099
	<hr/> <hr/>

LIABILITIES

Accounts Payable	\$ 22,914
Accrued Liabilities	6,032
	<hr/>
Total Liabilities	28,946
	<hr/>

FUND BALANCES

Restricted for:	
Culture and Recreation	263,153
	<hr/>
Total Fund Balances	263,153
	<hr/>
Total Liabilities and Fund Balances	\$ 292,099
	<hr/> <hr/>

The accompanying notes are an integral part of this statement.

Wildomar Measure Z Park Fund
Statement of Revenues, Expenditures and Changes in Fund Balances
Governmental Fund
For the Year Ended June 30, 2020

REVENUES

Intergovernmental	\$ 357,237
Charges for Services	23,948
Use of Money and Property	<u>214</u>
Total Revenues	<u>381,399</u>

EXPENDITURES

Current:	
General Government	1,632
Culture and Recreation	<u>357,338</u>
Total Expenditures	<u>358,970</u>

Excess (Deficiency) of Revenues Over (Under) Expenditures	22,429
--	--------

Fund Balances - Beginning of Year	<u>240,724</u>
-----------------------------------	----------------

Fund Balances - End of Year	<u><u>\$ 263,153</u></u>
-----------------------------	--------------------------

The accompanying notes are an integral part of this statement.

Wildomar Measure Z Park Fund
Notes to Financial Statements
June 30, 2020

1) SUMMARY OF SIGNIFICANT ACCOUNTING POLICIES

a. Description of the Reporting Entity

The Wildomar Measure Z Park Fund was established on November 6, 2012, pursuant to voter-approved annual parcel assessment to assist in the funding of park operations and related activities. On February 13, 2013, the City Council approved Resolution 2013-5 establishing the Measure Z Oversight and Advisory Committee and appointing 5 residents as committee members.

The Measure Z Park Fund is included as a special revenue fund of the City of Wildomar (the City) and, accordingly, the accompanying fund financial statements are included as a special revenue fund of the basic financial statements prepared by the City. The accompanying financial statements are intended to reflect the financial position of operations for the Measure Z Park Fund only and do not purport to, and do not, present the financial position of the City of Wildomar, California. Separate financial statements are prepared for the City of Wildomar, and may be obtained from the City.

b. Measurement Focus, Basis of Accounting, and Financial Statement Presentation

Governmental fund financial statements are reported using the current financial resources measurement focus and the modified accrual basis of accounting. Revenues are recognized as soon as they are both measurable and available. Revenues are considered to be available when they are collectible within the current period or soon enough thereafter to pay liabilities of the current period. For this purpose, the government considers revenues to be available if they are collected within 60 days of the end of the current fiscal year. Expenditures generally are recorded when a liability is incurred, as under accrual accounting. However, debt service expenditures, as well as expenditures related to compensated absences and claims and judgments, are recorded only when payment is due.

When both restricted and unrestricted resources are available for use, it is the Fund's policy to use restricted resources first, and then unrestricted resources as they are needed.

c. Assets, Deferred Outflows/Inflows of Resources, Liabilities, and Net Position or Equity

Cash and Investments

The City's cash and cash equivalents are considered to be cash on hand, demand deposits, and short-term investments with original maturities of three months or less from the date of acquisition. For financial statement presentation purposes, cash and investments are shown as both restricted and unrestricted cash and investments in the governmental funds.

Investments are reported at fair value. The City's policy is to hold investments until maturity or until market values equal or exceed cost. The State Treasurer's Investment Pool operates in accordance with appropriate state laws and regulations. The reported value of the pool is the same as the fair value of the pool shares.

Wildomar Measure Z Park Fund
Notes to Financial Statements
June 30, 2020

1) SUMMARY OF SIGNIFICANT ACCOUNTING POLICIES - Continued

c. Assets, Deferred Outflows/Inflows of Resources, Liabilities, and Net Position or Equity - Continued

Deferred Outflows/Inflows of Resources

In addition to assets, the balance sheet will sometimes report a separate section for deferred outflows of resources. This separate financial statement element, *deferred outflows of resources*, represents a consumption of fund balance that applies to a future period(s) and so will *not* be recognized as an outflow of resources (expense/expenditure) until then. Currently, the Fund does not report any deferred outflows.

In addition to liabilities, the balance sheet will sometimes report a separate section for deferred inflows of resources. This separate financial statement element, *deferred inflows of resources*, represents an acquisition of fund balance that applies to a future period(s) and so will *not* be recognized as an inflow of resources (revenue) until that time. Currently, the Fund does not report any deferred inflows.

Compensated Absences

The dollar value at June 30th of all vacation and sick leave hours is accrued when incurred in the government-wide financial statements. A liability for these amounts is reported in governmental funds only if they have matured, for example, as a result of employee resignations and retirements.

Staff and management are unrepresented and have a compensation plan. The City Manager is governed by an employment agreement which includes the compensation rate and specified rules governing vacation and sick leave. All employees are provided with vacation and sick leave when taken, with a cash-out of unused/accrued leave upon termination. Maximum accrual limits for each category:

Vacation Leave	320 hours
Sick Leave	320 hours

Vacation pay is payable to employees at the time a vacation is taken or upon termination of employment. Unless otherwise governed by an employee agreement, staff may convert in May and November a maximum of 40 vacation hours into compensation.

Sick leave is payable when an employee is unable to work because of illness. Employees with continuous employment of five years or more may receive a payment of 50% of their unused sick leave when they separate without cause or retire at the then rate of compensation.

Wildomar Measure Z Park Fund
Notes to Financial Statements
June 30, 2020

1) SUMMARY OF SIGNIFICANT ACCOUNTING POLICIES - Continued

c. Assets, Deferred Outflows/Inflows of Resources, Liabilities, and Net Position or Equity - Continued

Fund Equity

In the fund financial statements, government funds report the following fund balance classification:

Nonspendable include amounts that cannot be spent because they are either (a) not in spendable form or (b) legally or contractually required to be maintained intact.

Restricted include amounts that are constrained on the use of resources by either, (a) external creditors, grantors, contributions, or laws of regulations of other governments or (b) by law through constitutional provisions or enabling legislation.

Committed include amounts that can only be used for specific purposes pursuant to constraints imposed by formal action of the government's highest authority, the City Council. The formal action that is required to be taken to establish, modify, or rescind a fund balance commitment is a resolution.

Assigned include amounts that are constrained by the government's intent to be used for specific purposes, but are neither restricted nor committed. The City Manager is authorized to assign amounts to a specific purpose, which was established by the governing body in Resolution No. 2011-32 approved on June 21, 2011.

Unassigned include the residual amounts that have not been restricted, committed, or assigned to specific purposes.

Use of Estimates

The preparation of financial statements in conformity with accounting principles generally accepted in the United States of America requires management to make estimates and assumptions that affect the reported amounts of assets, liabilities, and deferred outflows/inflows of resources, and disclosure of contingent assets and liabilities at the date of the financial statements and the reported amounts of revenues and expenditures/expenses during the reported period. Actual results could differ from those estimates.

Functional Classifications

Expenditures of the governmental funds are classified by function. Functional classifications are defined as Culture and Recreation which includes activities which provide recreation, cultural and educational services.

Wildomar Measure Z Park Fund
Notes to Financial Statements
June 30, 2020

1) SUMMARY OF SIGNIFICANT ACCOUNTING POLICIES -Continued

c. Assets, Deferred Outflows/Inflows of Resources, Liabilities, and Net Position or Equity - Continued

Encumbrances

Encumbrances are estimations of costs related to unperformed contracts for goods and services. These commitments are recorded for budgetary control purposes in the fund. Encumbrances represent the estimated amount of the expenditure ultimately to result if unperformed contracts in process at year-end are completed. They do not constitute expenditures or estimated liabilities.

Budget Basis of Accounting

Budgets for governmental funds are adopted on a basis consistent with generally accepted accounting principles (GAAP).

2) CASH AND INVESTMENTS

As of June 30, 2020, cash and investments were reported in the accompanying financial statements as follows:

Governmental Fund	\$ 0
-------------------	----------

The Measure Z Park Fund is pooled with the City of Wildomar's cash and investments in order to generate optimum interest earnings. The information required by GASB Statement No. 40 related to authorized investments, credit risk, etc. is available in the comprehensive annual financial report of the City.

3) FAIR VALUE MEASUREMENTS

Governmental Accounting Standards Board (GASB) Statement No. 72, Fair Value Measurements and Application, provides the framework for measuring fair value. The framework provides a fair value hierarchy that prioritizes the inputs to valuation techniques used to measure fair value with Level 1 given the highest priority and Level 3 the lowest priority. The three levels of the fair value hierarchy are as follows:

Level 1 inputs are quoted prices (unadjusted) in active markets for identical assets or liabilities that the organization has the ability to access at the measurement date.

Level 2 inputs are inputs other than quoted prices included within *Level 1* that are observable for the asset or liability, either directly or indirectly. *Level 2* inputs include the following:

- a. Quoted prices for similar assets or liabilities in active markets.

Wildomar Measure Z Park Fund
Notes to Financial Statements
June 30, 2020

3) FAIR VALUE MEASUREMENTS - Continued

- b. Quoted prices for identical or similar assets or liabilities in markets that are not active.
- a. Inputs other than quoted prices that are observable for the asset or liability (for example, interest rates and yield curves observable at commonly quoted intervals, volatilities, prepayment speeds, loss severities, credit risks, and default rates).
- b. Inputs that are derived principally from or corroborated by observable market data by correlation or other means (market-corroborated inputs).

Level 3 inputs are unobservable inputs for the asset or liability.

As explained in Note 2, the Measure Z Park Fund has its investments pooled with the City. The cash and investments reflected is a portion of the City's overall cash and investments. Refer to the City's financial statements for additional information relating to categorization of investment types.

4) COMMITMENTS AND CONTINGENCIES

As of June 30, 2020, in the opinion of the City's Administration, there are no outstanding matters which would have a significant affect on the financial condition of the funds of the City.

COVID-19

On March 11, 2020, the World Health Organization declared the novel strain of coronavirus (COVID-19) a global pandemic and recommended containment and mitigation measures worldwide. The pandemic continued subsequent to year end with certain restrictions required by the Governor of California, as well as local governments, which may affect revenue sources and also caused subsequent stock market volatility. The duration of the pandemic and the impact of COVID-19 on the City's operational and financial performance is uncertain at this time.

REQUIRED SUPPLEMENTARY INFORMATION

Wildomar Measure Z Park Fund
Notes to Required Supplementary Information
June 30, 2020

Budgetary Comparison Information

General Budget Policies

The City Council approves each year's budget prior to the beginning of the new fiscal year. Public hearings are conducted prior to its adoption by the Council. Supplemental appropriations, where required during the period, are also approved by the Council. In most cases, expenditures may not exceed appropriations at the function level. At fiscal year-end, all operating budget appropriations lapse.

Encumbrances

Encumbrances are estimations of costs related to unperformed contracts for goods and services. These commitments are recorded for budgetary control purposes in the fund. Encumbrances represent the estimated amount of the expenditure ultimately to result if unperformed contracts in process at year-end are completed. They do not constitute expenditures or estimated liabilities.

Budget Basis of Accounting

Budgets for governmental funds are adopted on a basis consistent with generally accepted accounting principles (GAAP).

Wildomar Measure Z Park Fund
Budgetary Comparison Schedule
Year Ended June 30, 2020

	Budgeted Amounts		Actual	Variance with
	Original	Final	Amounts	Final Budget
Budgetary Fund Balance, July 1	\$ 240,724	\$ 240,724	\$ 240,724	\$ -
Resources (Inflows):				
Intergovernmental	375,000	375,000	357,237	(17,763)
Charges for Services	55,100	25,100	23,948	(1,152)
Use of Money and Property	-	-	214	214
Amounts Available for Appropriations	670,824	640,824	622,123	(18,701)
Charges to Appropriations (Outflows):				
General Government	-	2,000	1,632	368
Culture and Recreation	558,600	537,400	357,338	180,062
Total Charges to Appropriations	558,600	539,400	358,970	180,430
Budgetary Fund Balance, June 30	\$ 112,224	\$ 101,424	\$ 263,153	\$ 161,729

